LANGAN

SITE OBSERVATION REPORT – Remedial Investigation – Day 02

PROJECT No.: 170698601 CLIENT: DATE: Thursday, 10 November 2022

PROJECT: 125 3rd Street Third Street Gowanus Owner. WEATHER: Sunny, 48-63 °F Wind: SW @ 0-5 mph

LOCATION: Brooklyn, New York LLC TIME: 6:00 a.m. – 5:00 p.m.

EQUIPMENT: Management Inc. Months Enriquez Castro

Geoprobe 54TL Drill Rig Langan: Ali Reach, William Bohrer, Gabe Enriquez Castro

Mini RAE 3000 x3 Eastern Environmental Solutions, Inc. (Eastern): Ernesto Santiago

TSI Dust Trak x2 and one assistant Hand tools

OBSERVATIONS, DISCUSSIONS, TEST RESULTS, ETC.:

Langan Engineering, Environmental, Surveying, Landscape Architecture and Geology, D.P.C. (Langan) was present to implement the Remedial Investigation (RI) in accordance with the New York State Department of Environmental Conservation (NYSDEC)-approved Remedial Investigation Work Plan (RIWP), dated 3 June, 2022.

Site Activities

- Eastern used a track-mounted drill rig (Geoprobe® 54TL DT) to advance four soil borings (SB10, SB11, SB12, and SB17) in Area of Concern (AOC) 1, 2, 3, and 4. Langan documented the investigation and continuously screened the recovered soil for total organic vapor concentrations using a photoionization detector (PID) and for visual and olfactory indications of environmental impacts (e.g., staining, odor).
 - o **SB10** was advanced to a depth of about 20 feet below grade surface (bgs). No visual, olfactory, or instrumental evidence of impacts was identified.
 - o **SB11** was advanced to a depth of about 20 feet bgs. No visual, olfactory, or instrumental evidence of impacts was identified.
 - SB12 was advanced to a depth of about 16 feet bgs (confining layer encountered at about 14.5 feet bgs).
 No visual, olfactory, or instrumental evidence of impacts was identified.
 - o **SB17** was advanced to a depth of about 20 feet bgs. No visual, olfactory, or instrumental evidence of impacts was identified.
- Eastern installed one monitoring well at SB10 as follows:
 - **MW10**: 2 feet of 2-inch-diameter polyvinyl chloride (PVC) riser pipe and 10-foot-long, schedule-40, 0.01-inch slotted 2-inch-diameter PVC screen installed to 12 feet bgs and finished with a locking J-plug and flush-mounted steel manhole cover set into concrete. The borehole annulus was backfilled with No. 0 Sand to about 1 feet bgs, followed by 1 feet of bentonite and sealed to grade with grout.

Sampling

- Langan collected the following remedial investigation soil samples for laboratory analysis. The samples were submitted to Alpha Analytical Laboratories (Alpha), a New York State Department of Health (NYSDOH) Environmental Laboratory Approval Program (ELAP)-certified laboratory under standard chain-of-custody protocols. Soil samples were submitted for the following analyses: Part 375 List and Target Compound List (TCL) volatile organic compounds (VOC), semi-volatile organic compounds (SVOC), polychlorinated biphenyls (PCB), herbicides, pesticides, Target Analyte List (TAL)/Part 375 List metals (including hexavalent/trivalent chromium), total cyanide, NYSDEC-list per- and polyfluoroalkyl substances (PFAS), and 1,4-dioxane.
 - o SB10 0-2
 - o SB10 3-5
 - o SB10_11-13
 - o SB11_0-2
 - o SB11_3-5
 - o SB11_11-13
 - o SB12_0-2




Langan Project No.: 170698601 Date: Thursday, 10 November 2022

- o SB12_3-5
- o SB12_11-13
- o SB17_0-2
- o SB17_2-4
- o SB17_15-17
- o SBEB01_111022
- o SBTB02_111022

Community Air Monitoring Plan (CAMP) Activities

• Langan implemented the CAMP at upwind and downwind locations to monitor VOCs and particulate matter less than 10 microns in size (PM10) during ground-intrusive work. 15-minute-average concentrations of VOCs and PM10 were not recorded above the action levels during the monitoring period. No fugitive dust or odors associated with intrusive activities were observed migrating off site. Recorded air monitoring data is presented on the following graph:



Anticipated Activities

Langan will continue with the remedial investigation.



Langan Project No.: 170698601 Date: Thursday, 10 November 2022

SITE PHOTOGRAPHS:



Photo 1: Eastern advancing soil boring SB11 (facing northeast).



Photo 2: Eastern advancing soil boring SB17 (facing southwest).

LANGAN

Langan Project No.: 170698601 Date: Thursday, 10 November 2022

